

# Test Report

No.: 64.190.25.3931.01-00

Dated: 2026-02-02



**Applicant:** Foshan YiFeng Electric Industrial Co., Ltd.  
**Address:** No. 898, Gao Ming Avenue East, He Cheng Blvd. GaoMing District, Foshan City, Guangdong Province, China.  
**Sample Submission:** The sample was submitted by applicant and identified.  
**Product Name:** Tripod  
**Identification/Style No.:** RL-DELTA  
**Order No.:** /  
**Manufacturer:** Foshan YiFeng Electric Industrial Co., Ltd.  
**Address:** No. 898, Gao Ming Avenue East, He Cheng Blvd. GaoMing District, Foshan City, Guangdong Province, China.  
**Country of Origin:** /  
**Buyer:** /  
**Export to:** /  
**Brand name:** REYN AUDIO  
**Receipt Date of Sample:** 2025-11-05  
**Date of Testing:** From 2025-11-05 to 2026-01-28  
**Test Result:** Refer to the data listed in following pages

## Test Specification(s) or Test Item(s):

1. Test according to the client's requirements

## Conclusions:

See test results

Hardline Laboratory

TÜV SÜD Certification and Testing (China) Co., Ltd.  
Guangzhou Branch

Tested By: Leon Huang

Leon Huang  
Test Engineer



Reviewed By: Pein Xu

Pein Xu  
Designated Reviewer

### Note:

- (1) The TÜV SÜD Certification and Testing (China) Co., Ltd. "General Terms & Conditions" applied.  
Any use for advertising purposes must be granted in writing. This technical report may only be quoted in full. This report is the result of a single examination of the object in question. It does not imply a general statement regarding the quality of products from regular production. For further details please see "Testing, Certification, Validation and Verification Regulations", chapter A-3.3.  
For full version, please visit: EN : <https://www.tuvsud.cn/zh-cn/resource/terms-and-conditions---en> ; SCN: <https://www.tuvsud.cn/zh-cn/terms-and-conditions> ; TCN: <https://www.tuvsud.com/zh-tw/terms-and-conditions>  
(2) The results relate only to the items tested.  
(3) The test report shall not be reproduced except in full, without the written approval of the laboratory.

Laboratory:  
B1/F. of Building A2, Building D1, No.63,  
Chuangqi Road, Shilou, Panyu District,  
Guangzhou, Guangdong, China 511447

Telephone : +86 20 3832 0668  
Telefax : +86 20 3832 0478  
<https://www.tuvsud.com>

Regd. Office:  
TÜV SÜD Certification and Testing (China) Co., Ltd.  
Guangzhou Branch 5F, Communication Building, 163  
Pingyun Rd, Huangpu West Ave. Guangzhou  
510656P.R. China

Page 1 of 4

## Description of the test subject:

1	Product Description	Tripod
2	Dimensions / Weight	606×304×105mm/10kg

Sample Photo(s)







## Test Results:

## 1. Tensile test according to client's requirements

Item	Requirement-Test	Measuring result-Remark
1	<b>Tension test</b> Apply suitable clamps firmly fix the product to the test machine. Start the test machine with the rate of 100 mm per minute; Until the force reaches 131000 N, then remove the tension. Observe and record any breakage, component fracture after test.	No damage or component fracture was found after the tension test in two states.

## Testing photo(s):

	
During test	Testing curve
	
During test	Testing curve

## Remark:



1. The test results exclusively based on the submitted sample.
2. Tripod load capacity is expected to reach 130985N and the actual test force reaches 131000N, so the test force is greater than the expected force.
3. Specific requirement of test report as per clause 7.8.3 of CNAS-CL01-2018 or other accreditation scheme, such as: remark of subcontract information or on-site testing information.

**Disclaimer Measurement Uncertainty:**

Unless otherwise agreed upon, Pass or Fail verdicts are given based on the measured values without any considerations of measurement uncertainties.

Please note, every test method has a measurement uncertainty which has been evaluated by the laboratory according to ISO/IEC 17025 requirements.

By taking measurement uncertainties into account it might happen that measured values can neither be assessed as PASS nor as FAIL.

-End of Test Report-

